

HEAT SIPHON SERVICE LABOR PRICE SHEET

Standard Hourly Rate \$89.00

The following rates are for work performed by FACTORY AUTHORIZED SERVICE TECHNICIANS of United States ThermoAmp Inc. These prices are for LABOR ONLY to perform the following service repairs in the field or at the Factory based on the above Standard Labor Rate. They DO NOT INCLUDE any charges for parts, refrigerant, other expendable materials or any travel or trip charges that may be applicable to the task listed in accordance with the warranty terms and conditions in effect at the time service is performed. These prices are subject to change without notice.

ID#	Task	Std Hrs	Price	Notes
1	Replace Capacitors (either or both)	0.75	\$66.75	
2	Replace Compressor	3.00	\$267.00	
3	Replace Contactor	0.75	\$66.75	
4	Replace Fan Motor	1.00	\$89.00	
5	Replace Heat Exchanger	3.00	\$267.00	
6	Replace High Pressure Switch	2.00	\$178.00	
7	Replace Lo Pressure Switch	2.00	\$178.00	
8	Replace Thermostat	0.75	\$66.75	
9	Replace Time Delay	0.75	\$66.75	
10	Replace Transformer	0.75	\$66.75	
11	Replace TXV/Filter Dryer	0.75	\$66.75	
12	Replace Water Pressure Switch	0.75	\$66.75	
13	Added Hard Start Kit	0.75	\$66.75	
14	Change Out Unit	1.50	\$133.50	
15	Diagnostic-Misc.	0.50	\$44.50	
16	Diagnostic-noise/cycling/no start/no heat	0.50	\$44.50	
17	Diagnostic-other	0.50	\$44.50	
18	Diagnostic-tripping breaker	0.50	\$44.50	
19	Diagnostic-water leak	0.50	\$44.50	
20	Repair Burnt wires on compressor	0.75	\$66.75	
21	Repair Freon Leak-at isolation fittings	1.00	\$89.00	
22	Repair Freon Leak-other except evap fins	1.00	\$89.00	
23	Repair Water Leak-top of heat exchanger	1.00	\$89.00	
24	Replace Bottom Cap	1.50	\$133.50	
25	Diagnostic-running not heating	0.50	\$44.50	
26	Replaced schrader valve	0.75	\$66.75	
27	Replaced Digital Player Board	0.75	\$66.75	
28	Updated Digital Player Software	0.25	\$22.25	
29	Diagnotic Player Cy H	0.25	\$22.25	
30	Diganostic Player Cy L	0.25	\$22.25	
31	Replaced Tstat Well	0.75	\$66.75	
32	Wedged Thermostat Bulb	0.50	\$44.50	